



## Enabling AutoTurn and GuidSign in ORD

1. Open any ORD file.
2. In the Search bar in the top right corner of the ORD window type key-in and select the Key-In option. This will open the Key-In window.



3. On the Key-In window type **mdl load "C:\Program Files\Transoft Solutions\AutoTURN 11\atcn.ma"** and hit Enter to enable AutoTurn. To enable GuidSign type **mdl load "C:\Program Files\Transoft Solutions\GuideSIGN 8\gscn.ma"** and hit Enter.



4. After the software has loaded a new tab for it will be on the Drawing workflow.

